



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program January 29, 2013

Reviewed: 

<b>Mine Name:</b> Bohman Ranch	<b>Permit Number:</b> S/029/0006
<b>Operator Name:</b> Brent Bohman	<b>Inspection Date:</b> November 03, 2010
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 3:00 PM
<b>Other Participants:</b> Brent Bohman	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>


**Bond Renewal Date:** 08-21-2012 **Bond Amount:** \$500 **Permit fee** is delinquent for several years.

**Purpose of Inspection:** Routine annual Inspection. This site has had no documentation or written inspections.

**Inspection Summary:** Site has been plucked for landscape rock. Footprint of disturbance is small. There are no highwalls, trash, erosional problems, or site grading problems. No weeds were noted in the mined areas. The area adjacent to the house has been successfully revegetated.

Photos were taken to document site conditions.

**Conclusions and Recommendations:** Overall operator understands resource conservation and has mined in a responsible manner. Bond amount is not sufficient for a 3<sup>rd</sup> party reclamation. Bond amount is past due for escalation, but the Division is willing to negotiate a reasonable bond amount. Surface rights are controlled by Operator and there has been no history of complaints to the Division. OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature** 

LAH:eb

cc: Brent Bohman

O:\M029-Morgan\S0290006-BohmanRanch\inspections\Insp-11032010.doc





Overview of current mine site



Overview of one mining site



Close up of current mine site



Successful revegetation adjacent to house